



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D3913-041
Job Sheet 193819



Part No: D3913-041

Job Qty: 1 pcs

Part Name: Long Basket Base Assembly, 350



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 4/23/19

Job Tracking No:

Due Date: 5/10/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG D4020 REV A SHEET 4, D3913 REV D SHEETS 1,2,3,4,5 IPP Rev:A new issue DD 10.03.19 verified by:EC IPP Rev:B chg qty's DD 10.04.12 verified by:EC IPP REV:C 12.07.24 AS PER DWG REV.B DD VERF:EC IPP REV:D 13.08.21 DWG REV.C / ECN 13-624 DD VERF:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
100	Large Fab - Basket - 1	1 pcs	5/10/19		0.00	16.00	Large Fab - 1		
							Large Fab - 10		
							Large Fab - 2		
							Large Fab - 3		
							Large Fab - 4		DAS
							Large Fab - 5		43
							Large Fab - 6		9-89
							Large Fab - 7		
							Large Fab - 8		
110	QC 9	1 pcs	5/10/19		0.00	0.00	QC 9 - 10		
							QC 9 - 18		
							QC 9 - 24	DAS	MAY 22 2019
							QC 9 - 43	24	
							QC 9 - 50	9-89	
							QC 9 - 9		
120	QC 5	1 pcs	5/10/19		0.00	0.00	QC 5 - 10		
							QC 5 - 12		
							QC 5 - 17		
							QC 5 - 18		
							QC 5 - 19		
							QC 5 - 22		
							QC 5 - 24	DAS	MAY 22 2019
							QC 5 - 3	24	
							QC 5 - 43	9-89	
							QC 5 - 49		
							QC 5 - 51		
							QC 5 - 58		
							QC 5 - 68		
							QC 5 - 9		



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S182315



Part: D3913-041

Job No: 193819

Serial No/Batch: S182315

Revision:

Inspector:

Exp Date:

Instructions: Various STC's

Date: 05/18/19

Plex 4/23/19 8:36 AM Dart.lajeunesse.marie

				QC 5 - 50	
				QC 5 - 30	
				QC 5 - 40	
125 Handfinish - 2-1 Pressure-B4B	1 pcs	5/10/19	0.00 0.29	Handfinish - 2 - 1 - B4B	BEB 19-05-22.
				Handfinish - 2 - 2 - B4B	
				Handfinish - 2 - 3 - B4B	
				Handfinish - 2 - 4 - B4B	
130 Powdercoat - 2 White Gl(S)-B4B	1 pcs	5/10/19	0.00 0.93	Powdercoat - 1 - B4B	
				Powdercoat - 2 - B4B	
				Powdercoat - 3 - B4B	BK 19-05-22.
				Powdercoat - 4 - B4B	
				START: 2:00 OUT: 3:35 FINISH: 2:15	
135 Packaging 1-1 - Pick Kit - B4B	1 pcs	5/10/19	0.00 0.00	Packaging 1 - 1 - B4B	
				Packaging 1 - 2 - B4B	
				Packaging 1 - 3 - B4B	
				Packaging 1 - 4 - B4B	
				Packaging 1 - 5 - B4B	
				Packaging 1 - 6 - B4B	
				Packaging 1 - 7 - B4B	
				Packaging 1 - 8 - B4B	
				Packaging 1 - 9 - B4B	
				Packaging 1 - 10 - B4B	
				Packaging 1 - 11 - B4B	
				Packaging 1 - 12 - B4B	
				Packaging 1 - 13 - B4B	
				Packaging 1 - 14 - B4B	
				Packaging 1 - 15 - B4B	
				Packaging 1 - 16 - B4B	BEB 19-05-22.
				Packaging 1 - 17 - B4B	
				Packaging 1 - 18 - B4B	
				Packaging 1 - 19 - B4B	
				Packaging 1 - 20 - B4B	
				Packaging 1 - 21 - B4B	
				Packaging 1 - 22 - B4B	
				Packaging 1 - 23 - B4B	
				Packaging 1 - 24 - B4B	
				Packaging 1 - 25 - B4B	
				Packaging 1 - 26 - B4B	
				Packaging 1 - 27 - B4B	
				Packaging 1 - 28 - B4B	
				Packaging 1 - 29 - B4B	
				Packaging 1 - 30 - B4B	
				Packaging 1 - 31 - B4B	
				Packaging 1 - 32 - B4B	
				Packaging 1 - 33 - B4B	
				Packaging 1 - 34 - B4B	
				Packaging 1 - 35 - B4B	
				Packaging 1 - 36 - B4B	
140 QC 3	1 pcs	5/10/19	0.00 0.00	QC 3 - 10	
				QC 3 - 13	
				QC 3 - 15	
				QC 3 - 17	
				QC 3 - 18	
				QC 3 - 2	
				QC 3 - 28	
				QC 3 - 3	
				QC 3 - 30	

						QC 3 - 34	
						QC 3 - 36	
						QC 3 - 41	
						QC 3 - 51	
						QC 3 - 58	
						QC 3 - 59	AT VM BEB 19-05-23
						QC 3 - 68	
						QC 3 - 9	
						QC 3 - 40	
						QC 3 - 19	
150 Handfinish - 4-1-Assembly-B4B	1 pcs	5/10/19	0.00	0.50		Handfinish - 4 - 1 - B4B	M 14-5-20
						Handfinish - 4 - 10 - B4B	
						Handfinish - 4 - 11 - B4B	
						Handfinish - 4 - 12 - B4B	
						Handfinish - 4 - 13 - B4B	
						Handfinish - 4 - 14 - B4B	
						Handfinish - 4 - 15 - B4B	
						Handfinish - 4 - 2 - B4B	
						Handfinish - 4 - 3 - B4B	
						Handfinish - 4 - 4 - B4B	
						Handfinish - 4 - 5 - B4B	
						Handfinish - 4 - 6 - B4B	
						Handfinish - 4 - 7 - B4B	
						Handfinish - 4 - 8 - B4B	
						Handfinish - 4 - 9 - B4B	
160 QC 5	1 pcs	5/10/19	0.00	0.00		QC 5 - 10	DAS 19 9-00
						QC 5 - 12	
						QC 5 - 17	
						QC 5 - 18	
						QC 5 - 19	
						QC 5 - 22	
						QC 5 - 24	
						QC 5 - 3	
						QC 5 - 43	
						QC 5 - 49	
						QC 5 - 51	
						QC 5 - 58	
						QC 5 - 68	
						QC 5 - 9	
						QC 5 - 50	
						QC 5 - 30	
						QC 5 - 40	
170 Packaging 3-1 - Stock - B4B	1 pcs	5/10/19	0.00	0.00		Packaging 3 - 1 - B4B	M 14-5-20
						Packaging 3 - 2 - B4B	
						Packaging 3 - 3 - B4B	
						Packaging 3 - 4 - B4B	
						Packaging 3 - 5 - B4B	

				Packaging 3 - 6 - B4B	
				Packaging 3 - 7 - B4B	
				Packaging 3 - 8 - B4B	
				Packaging 3 - 9 - B4B	
				Packaging 3 - 10 - B4B	
				Packaging 3 - 11 - B4B	
				Packaging 3 - 12 - B4B	
				Packaging 3 - 13 - B4B	
				Packaging 3 - 14 - B4B	
				Packaging 3 - 15 - B4B	
				Packaging 3 - 16 - B4B	
				Packaging 3 - 17 - B4B	
				Packaging 3 - 18 - B4B	
				Packaging 3 - 19 - B4B	
				Packaging 3 - 20 - B4B	
				Packaging 3 - 21 - B4B	
				Packaging 3 - 22 - B4B	
				Packaging 3 - 23 - B4B	
				Packaging 3 - 24 - B4B	
				Packaging 3 - 25 - B4B	
				Packaging 3 - 26 - B4B	
				Packaging 3 - 27 - B4B	
				Packaging 3 - 28 - B4B	
				Packaging 3 - 29 - B4B	
				Packaging 3 - 30 - B4B	
				Packaging 3 - 31 - B4B	
				Packaging 3 - 32 - B4B	
				Packaging 3 - 33 - B4B	
				Packaging 3 - 34 - B4B	
				Packaging 3 - 35 - B4B	
				Packaging 3 - 36 - B4B	
180	QC 21 - SA	1 pcs	5/10/19	0.00 0.00	QC 21 - SA - 21
					QC 21 - SA - 70
					QC 21 - SA - 53
Part Op 100 - Weld per dwg A/R S.S. rod Batch: _____ 1- assemble ribs , weld as per dwg D3913 using DT9610A ***inspect Descriptions: before welding mesh*** 2-Cut D4020-1 base mesh and tack weld all mesh on basket as per dwg D3913 and trim mesh to fit if necessary and trim to clear fasteners holes on the ends 3- weld hinge (3) and Mounting brackets as per dwg D3913 ***take lid to locate hinge and bracket*** 4- Weld D4672-1 blanking plates as per dwg 110 - QC9- Inspect visual per QSI004- Fusion Welds 120 - QC5- Inspect part completeness to step on W/O 125 - Pressure Wash per QSI005 4.3/ Clean and remove all markings 130 - White Gloss(Ref:4.3.5.2) per QSI005 4.3-Steel) 1- Plug holes and mask only interior of hinge (3) prior to powder coat 135 - Pick Kit 140 - QC3- Inspect Part Finish 150 - Assemble as per dwg - Pick Kit 160 - QC5- Inspect part completeness to step on W/O 170 - Identify as per dwg & Stock Location: _____ 180 - QC21- Final Inspection - Work Order Release					

DAG
21

MAY 29 2019

#009607

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D2581	Mounting Bracket	2 pcs (2 ea)	100-Large Fab - Basket - 1	5161219
D3913-1	Rib	1 pcs (1 ea)	100-Large Fab - Basket - 1	5163425
D3913-15	Wide Handle Plate	1 pcs (1 ea)	100-Large Fab - Basket - 1	5155103
D3913-3	Rib	1 pcs (1 ea)	100-Large Fab - Basket - 1	5168604
D3913-7	Rib	2 pcs (2 ea)	100-Large Fab - Basket - 1	5169188
D3913-9	Hinge Rib	1 pcs (1 ea)	100-Large Fab - Basket - 1	5165737
D3916-041	Rib Assembly	2 pcs (2 ea)	100-Large Fab - Basket - 1	5172042 5178465
D3916-5	Light Rib	3 pcs (3 ea)	100-Large Fab - Basket - 1	5172021
D4016-1	Hinge Half, Base	3 pcs (3 ea)	100-Large Fab - Basket - 1	5121276
D4017-7	Rib	3 pcs (3 ea)	100-Large Fab - Basket - 1	5173533
D4017-9	Rib	2 pcs (2 ea)	100-Large Fab - Basket - 1	5172411
D4020-11	End Mesh, Basket	2 pcs (2 ea)	100-Large Fab - Basket - 1	5179084
D4021-1	Handle Plate	3 pcs (3 ea)	100-Large Fab - Basket - 1	5170451
D4034-041	Aft Upper Rib Assembly	1 pcs (1 ea)	100-Large Fab - Basket - 1	5175136
D4034-043	Fwd Upper Rib Assembly	1 pcs (1 ea)	100-Large Fab - Basket - 1	5174542
D4672-1	Blanking Plate	2 pcs (2 ea)	100-Large Fab - Basket - 1	5160068
M304EX0.75-16F	Expanded Metal Flat SS	32 sf (32 ea)	100-Large Fab - Basket - 1	5162977
AN3-10A	Bolt	6 Ea (6 ea)	150-Handfinish - 4-1-Assembly-B4B	5166831
D2931	Bumper	2 pcs (2 ea)	150-Handfinish - 4-1-Assembly-B4B	F86435
MS20600-AD4W3	Cherry Rivet	2 Ea (2 ea)	150-Handfinish - 4-1-Assembly-B4B	5155667
MS21042L3	Nut	6 Ea (6 ea)	150-Handfinish - 4-1-Assembly-B4B	5158921
NAS1149F0332P	Washer	12 Ea (12 ea)	150-Handfinish - 4-1-Assembly-B4B	5170865
D4021-5	Blanking Plate	2 pcs (2 ea)	150-Handfinish - 4-1-Assembly-B4B	5157462
NAS1149FN832P	Washer	2 Ea (2 ea)	150-Handfinish - 4-1-Assembly-B4B	5136364

Job Allocations

009950

Operation	Component Part	Required	Inventory	Allocated
100-Large Fab - Basket - 1	D2581	2	25	0
	D3913-1	1	9	0
	D3913-15	1	11	0
	D3913-3	1	1	0
	D3913-7	2	14	0
	D3913-9	1	4	0
	D3916-041	2	9	0
	D3916-5	3	9	0
	D4016-1	3	51	0
	D4017-7	3	73	0
	D4017-9	2	12	0
	D4020-11	2	2	0
	D4021-1	3	19	0
	D4034-041	1	1	0
	D4034-043	1	1	0
	D4672-1	2	17	0
	M304EX0.75-16F	32	1,048	0
	AN3-10A	6	232	0
	D2931	2	739	0
150-Handfinish - 4-1-Assembly-B4B	D4021-5	2	32	0
	MS20600-AD4W3	2	530	0
	MS21042L3	6	3,426	0
	NAS1149F0332P	12	5,225	0
	NAS1149FN832P	2	2,375	0

Part Specifications

Specifications could not be found.

Plex 4/23/19 8:36 AM Dart.lajeunesse.marie

Entered: _____ Date: _____



WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____ Part No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐	DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Eng. (Non-AW) ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Engineering ☐ Water Jet ☐ Supplier ☐ Quality ☐			
Date :	Sequence #:	QTY Affected :		MRB (QSI042)	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor		
			QC / QA Coordinator		
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY ☐ Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread			
Other/Details:					